


STRUCTURAL SOUNDNESS CERTIFICATE

This is certify that I have inspected KADAPA PUBLIC SCHOOL located in D.No: 105/90-9-2 with Assessment number 1013085297, Sy.No. 18/1, Pullampalli Road, T.Ramachandra puram (V), Kadapa, Kadapa Municipal Corporation, Y.S.R.Dist. It is well Ventilated and Structurally Sound, the building provided with separate class rooms for each class with well ventilation and alighting there is plinth of open for the children to play and good condition and suitable for accommodation.

Place : KADAPA

Date : 25-04-2019


Signature with Seal 25/4/19

DEPUTY EXECUTIVE ENGINEER
MUNICIPAL CORPORATION
KADAPA.

STRUCTURAL STABILITY CERTIFICATE


This to certify that the structural designs for the proposed construction of commercial Primary School building with RCC framed structure consist of Ground+1 upper floors At Do.no.:105/90-9-2, Pullampalli road, T.Ramachandrapuram village, in S.No.: 18/1 , Kadapa. Belonging **Smt C.Naveena**, Has been designed by me confirming to relevant IS codes. The bearing capacity of soil available at the site as ore soil test report is 22 T/m². The proposed structure is stable and safe.

This certificate is invalid if any subsificant modifications are made to the structure in any manner. Further the certificate in invalid in the case of misrepresentation of data, suppression of records by builder (or) owner (or) the agent.

Date : 5/12/18

Place: Kadapa.

Licensed Structural Engineer



Er. A. MOHAN, M.Tech., MIE
Licensed Structural Engineer
License No. 0020/TP/KMC/G1/2015